ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL Manual No Procedure No Page **Effective Date** Organization

5-21000-OPS-GT Table of Contents, Rev 8 1 of 3 12/02/91 **Environmental Management**

THIS IS ONE VOLUME OF A SIX VOLUME SET WHICH INCLUDES.

VOLUME I FIELD OPERATIONS (FO) VOLUME II GROUNDWATER (GW) VOLUME III GEOTECHNICAL (GT)

DOCUMENT

VOLUME IV SURFACE WATER CONTROL VOLUME V ECOLOGY (EE) VOLUME VI. AIR (AP)

STS PLANT EG&G - Ran +

ENVIRONMENTAL MAKA ALMENT DEPARTMENT

TABLE OF CONTENTS FOR VOLUME III GEOTECHNICAL This is a RED Stamp

New Proc <u>No</u>	Old Proc No.	<u>Title</u>	Rev No	Effective Date
GT 01	3 1	Logging Alluvial and Bedrock Material	1	8/30/91
DCN 91 01		Recording lithologic descriptions and securing core boxes	1	11/15/91
GT 02	3 2	Drilling and Sampling Using Hollow Stem Auger Techniques	1	8/30/91
DCN 91 01		Unconsolidated core samples need not be peeled before sampling	1	10/29/91
DCN 91 02		Correction of well location for low Alluvial thickness	1	11/6/91
DCN 91 03		Ten foot long core barrels	1	11/15/91
GT 03	3 3	Isolating Bedrock From the Alluvium with Grouted Surface Casing	1	8/30/91
DCN 91 01		Change in criteria for cement grouting	1	10/02/91
DCN 91 02		Grout procedure clarification	1	10/28/91

ADMIN RECORD

REVIEWED FOR CLASSIFICATION/UCNI-F J Curran Date _

A-SW-000201

ROCKY FLATS PLANT	Manual No	5-21000-OPS-GT
EMD OPERATING	Procedure No	Table of Contents, Rev 8
PROCEDURES MANUAL	Page	2 of 3
	Effective Date	12/02/91
	Organization	Environmental Management

New Proc <u>No</u>	Old Proc <u>No</u>	<u>Title</u>	Rev No	Effective Date
GT 04	3 4	Rotary Drilling and Rock Coring	1	8/30/91
DCN 91 01		Core barrel decontamination	1	10/22/91
DCN 91 02		Clarification of measuring tape decontamination requirements	1	10/29/91
GT 05	3 5	Plugging and Abandonment of Boreholes	1	8/30/91
DCN 91 01		Surface casing classification	1	10/22/91
GT 06	3 6	Monitoring Wells and Piezometer Installation	1	8/30/91
DCN 91 01		Industry Standard is 1 foot into Bedrock	1	10/15/91
DCN 91 02		For the Sitewide Program, Claystone Smearing does not seem to be a problem	1	10/15/91
DCN 91 03		Superseded by DCN 91 06	1	11/08/91
DCN 91 04		Low Alluvial thickness wells	1	11/06/91
DCN 91 05		Superseded by DCN 91 08	1	11/06/91
DCN 91 06		Change in filter pack guidance	1	11/08/91
DCN 91 07		Decontamination for site-wide geological characterization	1	11/15/91
DCN 91 08		Figure replacement (GT 6-1)	1	11/15/91
GT 07	3 7	Logging and Sampling of Test Pits and Trenches	1	8/30/91
GT 08	3 8	Surface Soil Sampling	1	8/30/91
DCN 91 01		Clarification supplementation of GT 08 - Surface Soil Sampling	1	11/26/91
GT 09	3 9	Soil Gas Sampling and Field Analysis	1	8/30/91

ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL		Prod UAL Pag Effe	ual No cedure No e ctive Date anization	5-21000-OPS-G Table of Contents, Rev 3 of 12/02/9 Environmental Manageme	
New Proc No.	Old Proc No	<u>Title</u>		Rev <u>No</u>	Effective Date
GT 10	3 10	Borehole Clearing		1	8/30/91
GT 11	3 11	Plugging and Abandonm	ent of Wells	1	8/30/91
GT 15	3 15	Geophysical Borehole Lo	ogging	1	8/30/91
DCN 91 01		No Hole will be left Unlog of the day	ged at the end	1	10/15/91
GT 17	3 17	Land Surveying		1	8/30/91
GT 18	3 18	Surface Geophysical Sur	veys	1	8/30/91

8/30/91

8/30/91

1

Field Gas Chromatographs

Procedures for Soil Interstitial Water Sampling and Sampler Installation

GT 19

GT 20

3 19

3 20

ENVIRONMENTAL RESTORATION AND WASTE MANAGEMENT DOCUMENT CHANGE NOTICE (DCN)

PRESS FIRMLY AND PRINT LEGIBLY OR TYPE PROPOSED CHANGES TO INSURE DUPLICATE IS MADE ON ALL COPIES

DOCUMENT NUMBER Procedure No GT.8,5-21000-OPS-GT

PAGE 1 OF 2

[T	n m
TTILE				DATE	DCN NUMBER '
Surface Soil	Sampling			November 22, 1991	GT 8-91-1
EXPIRES Feb	urary 25, 1992			C	
LIMITATIONS	OU2		1	- isi	MENT
Item Number	Page	Step or Paragraph		(Use DCN CONTINUATION SHEET for ad	ditional space)
(1)	4 of 16	Section 50, Paragraph 3		according to GT1 will not be required Particle si chment 10, Surficial Soil Sampling Plan of the OU 1, RO)	-
(2)	5 of 16	2nd Bullet	from 25 subsamp	may be used instead of stainless steel or plastic Si de points generally amounts to about 16 ounces (vol composite laboratory samples Two-ounce glass jams	lume) or less, 16-ounce glass jars
(3)	N/A	Subsection 5 2 1	Duplicate sample and placing the d containerized follo	ot currently address the procedure to be used for one is will be obtained by offsetting the primary subsame uplicate subsamples in a separate jar. The duplication owing the same procedures as for the primary same in the Field Sampling Plan (FSP) or the Quality A.	ple location 0.5 to 2 feet upwind e sample will be composited and ole The frequency of duplicate
(4)	N/A	Subsection 5 2 1	locations of the 2 locations within e plots, the subsamperiphery of the padjacent plot. Sir 33 feet from the plot layout. Num the southwest corup one row and d. All plot corners w.	to to currently address a procedure to be used for detection of the subsample points within each sample plot. The track sample plot will be described by an evenly space ple target locations are described by a 132-foot grid plot are 66 feet from the plot edge, or 132 feet from nilarly, for 2.5-acre plots, the spacing is reduced to plot boundary. See Item Number (5) of this DCN is being of the subsample points will start at the first ner unless site features dictate a different starting prown the next until all 5 rows of 5 points each have	arget locations of the 25 subsample ed grid. For example, for 10-acre. The subsample points around the in the subsample points in the 66 feet with the peripheral points for an example of a typical 10-acre. It point sampled (which will be at point), and continue consecutively been sampled. GT 17, Land Surveying)
			The subsample potential be reference point us. The subsample potential be none of the subsample points when the corner in distance measured 20, and 25. Distansubsample point to and distance meas. See Item Number the survey checks.	greence point for any given plot may consist of any given to the southwest corner to conform with consect will be documented on Form 3 &A onts will be surveyed by taping, use of a measuring ton compass. Regardless of the method used, surveyed made to verify the accuracy of the measurements mple points are offset, bearings will be measured with 1, 3, 5, 7, 8, 9, 11, 13, 15, 17, 18, 19, 21, 23, and 25, marker is within sight and when the subsample point enter will be made to the plot corners and boundary nice measurements will be made by pacing the perputor of the boundary and from this location to the plot contents is to enable documentation of the accuracy (5) of this DCN for an example of how these check indentifies a discrepancy of more than 30 feet, the streets indicate all subsample points are within 30 feet.	wheel, or by pacing, combined with by checks using the following. For an evenly spaced grid where with the Brunton compass from to the nearest plot corner marker it has not been offset. In addition, we from subsample points 5, 10, 15, andicular distance from the former. The purpose of the bearings by of the subsample point locations are will be documented. If any of subsample points will be remeasured.

ENVIRONMENTAL RESTORATION AND WASTE MANAGEMENT DOCUMENT CHANGE NOTICE (DCN) (Continued)

PRESS FIRMLY AND PRINT LEGIBLY OR TYPE PROPOSED CHANGES TO INSURE DUPLICATE IS MADE ON ALL COPIES

DOCUMENT NUMBER Procedure No. GT 8, 5-21000-OPS-GT

PAGE 2 OF 2


TITLE				DATE	DCN NUMBER
Surface Soil	Sampling			November 22, 1991	GT 8-91-1
EXPIRES Feb	urary 25, 1992				
LIMITATIONS	5 <u>OU2</u>				
Item Number	Page	Step or Paragraph		Changes (Use DCN CONTINUATION SHEET for add	ditional space)
			plot If pavement integrity or endant from a smaller are this can not be do be documented or accuracy of 30 fee	tions of subsample points may be revised when obset, disturbed ground, or other obstacles are present ager the samplers, the grid may be adjusted to allow the action of a protection of a plot can not be a sketch complete enough to be able to relocate of a survey checks as described above will be made a points. See Item Number (5) of this DCN for an experience of the survey of t	that would jeopardize sample to the 25 subsamples to be obtained cing will be maintained, however, sampled All offset locations will each subsample location within an to document the accuracy of the
(5)	16 of 16	Section 80 Form GT 8B		be updated to include a supplement. The Supplement completed form is attached to this DCN	ent to Form GT 8B and an
(6)	16 of 16	Section 80	An RFEDS Surfa RFEDS	ce Soil Sample Collection Form (FO 14E) will be u	sed to document input of data into

Justification (Reason for change - Provide numbers to reference corresponding items above)

- (1) To maintain consistency with OU2 Alluvial Work Plan
- (2) To be consistent with QAPjP
- (3) To supplement SOP
- (4) To supplement SOP
- (5) To supplement Form GT 8B
- (6) For input to RFEDS

Concurrence	Organization	Req	Date	Concurrence	Organiza	ation	Req	Date
Stow	фарм	х	11/26/11	Michael Lyan			\mathcal{X}	11/25/91
11 7 . 1 /	rud EOM	x	11-25-91	Six A. M	i cm/R	PD	×	11/25/11
			ļ		•			
13 Approval of	Responsible Ma	nager	14 Date	15 Is Posting R	equired	16 if Yes, b	y what date	17 Date Posted

ROCKY FLATS FIELD ACTIVITIES REPORT SURFACE SOIL SAMPLING



COORDINATES OF SW CORNER

Ν


Ε

T1=	T6=	T11=	T16=	T21=
T2=	T7=	T12=	T17=	T22=
T3=	T8=	T13=	T18=	T23=
T4=	T9=	T14=	T19=	T24=
T5=	T10=	T15=	T20=	T25=

ROCKY FLATS FIELD ACTIVITIES REPORT SURFACE SOIL SAMPLING

EXAMPLE

PROJECT NUMBER
PROJECT NAME
PLOT NUMBER
SAMPLERS



COORDINATES OF SW CORNER

N XDXXX

E PXPXC

T2 = 000 $T7 = 000$ $T12 = 000$ $T17 = 000$ $T17 = 000$ $T18 = 000$	$T_{1}=\phi 84$	T6= \$854	T11= \$913	T16= 6935	T21= Ø95 7
T3= \$6 AA T8= \$9\$3 T13= \$9\$\$ T18= \$9\$\$ T23=1\$1\$		T7= \$899	T12= \$917	T17 = 6944	T22= 1/195
	T3= Ø 8 44	T8= p9p3	T13= (192)	T18= Ø95\$	T23=1010
14 = 40, $13 = 1040$	T4= \$ 8 66	T9= 09 05	T14= 6922	T19= 495Z	T24=1/21-1
T5= \$ 849 T10= \$968 T15= \$925 T20= \$954 T25=1 \$\tilde{Z}\$1	T5= \$ 849	7	T15= 6925	T20= \$954	T25=1 Ø21

RFEDS SURFACE SOIL SAMPLE COLLECTION FORM

Project Number Sample Number North or Y Boring Number	EM	AD		Name Type East or X	EMAD SO	
Collection Date Collection Time Sample Location	1 1			Quarter		Dry
Composite	(Y/N)					
Composite Desc						
QC Type				Partner		
Collection Method						
Sample Team Leader			i .			
Member						
Member						
Volume Collected			Units			
Prapared By						
Project Number	EMA	.D		Name	EMAD	
Sample Number						
Depth of take	Start		End			
·		ın				
		m				
		m				
		ın				

Headspace Reading Comments